

Measuring Radius Corners

Radius corners must be squared before measuring. Use 2 straight edges to form an imaginary square corner, mark where the edges meet as Point 1. Measure from the imaginary corner (Point 1) to Point 2. Refer to the Example to correctly measure your radius corners.

Example

